



MOUNTING HOLE $\phi 3.3$
THICKNESS 1.6



BADY

MOUNTING HOLE $\phi 3.2$
THICKNESS 1.8



PIN

NOTE: 1. SHRINKING IS NORMAL STATUS.
內縮屬正常現象。
2. MADE OF EQUIVALENT MATERIAL.
可使用同等材質。



康揚企業股份有限公司
KANG YANG HARDWARE ENTERPRISE CO., LTD.
康揚塑膠(東莞)有限公司
KANG YANG PLASTIC(DONG GUAN)CO.,LTD.
康哲電腦配件(吳江)有限公司
KANG CHE COMPUTER COMPONENTS(WUJIANG)CO.,LTD.

PROPRIETARY AND CONFIDENTIAL THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF KANG YANG HARDWARE ENTERPRISE CO. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF KANG YANG HARDWARE ENTERPRISE CO. IS PROHIBITED. DO NOT SCALE DRAWING	DATE	TITLE		DWG. NO.	PART NO.	
	2019.12.17	SPACER SUPPORT		MSPB-8L	MSPB-8L	
	DRAWN	MATERIAL	COLOR	FINISH	SIZE	REV
	Terry	NYLON 66 UL94V-2	NATURAL		A4	A
CHECKED	APPROVED	UNLESS OTHERWISE SPECIFIED		SPEC. DWG.		
林祺翔	Kang	TOLERANCE: SEE ABOVE		SCALE: 4:1	UNIT mm	SHEET 1 OF 1