



HOLE IN CHASSIS

NOTE: 1. SHRINKING IS NORMAL STATUS.

內縮為正常現象。

2. MADE OF EQUIVALENT MATERIAL.

均可使用同等材質。

3. THE COLOR BATCH TEST REPORT IS ONLY FOR FIRST LOT TEST.

色母環保檢測報告, 僅提供原始測試報告。



康揚企業股份有限公司

KANG YANG HARDWARE ENTERPRISE CO., LTD.

康揚塑膠(東莞)有限公司

KANG YANG PLASTIC(DONG GUAN)CO.,LTD.

康哲電腦配件(吳江)有限公司

KANG CHE COMPUTER COMPONENTS(WUJIANG)CO.,LTD.

PROPRIETARY AND CONFIDENTIAL  
THE INFORMATION CONTAINED IN  
THIS DRAWING IS THE SOLE PROPERTY  
OF KANG YANG HARDWARE  
ENTERPRISE CO. ANY  
REPRODUCTION IN PART OR AS A  
WHOLE WITHOUT THE WRITTEN  
PERMISSION OF  
KANG YANG HARDWARE ENTERPRISE  
CO. IS PROHIBITED.

DATE  
2010.05.18

TITLE  
STRIKER

DWG. NO.  
DT-48B

PART NO.  
DT-48B(B)

DRAWN  
T.C

MATERIAL  
NYLON 66 UL94V-2

CHECKED

COLOR  
BLACK

FINISH

SIZE  
A4

SPEC. DWG

REV  
A

APPROVED

UNLESS OTHERWISE SPECIFIED  
TOLERANCE: SEE ABOVE

SCALE: 2:1

UNIT  
mm

SHEET 1 OF 1

DO NOT SCALE DRAWING