



HOLE IN P.C.B $\phi 3.05^{+0.05}_{-0}$
HOLE IN HEAT SINK $\phi 3.2^{+0.2}_{-0}$

PART NO.	MATERIAL	COLOR
HSR-93A(N)	NYLON 66 UL94V-2	NATURAL
HSR-93A(B)		BLACK
HSR-93AV0(B)	NYLON 66 UL94V-0	BLACK

NOTE:1. SHRINKING IS NORMAL STATUS.

內縮為正常現象。

2. MADE OF EQUIVALENT MATERIAL.

均可使用同等材質。

3. THE COLOR BATCH TEST REPORT IS ONLY FOR FIRST LOT TEST.

色母環保檢測報告, 僅提供原始測試報告。



康揚企業股份有限公司
KANG YANG HARDWARE ENTERPRISE CO., LTD.
康揚塑膠(東莞)有限公司
KANG YANG PLASTIC(DONG GUAN)CO.,LTD.
康哲電腦配件(吳江)有限公司
KANG CHE COMPUTER COMPONENTS(WUJIANG)CO.,LTD.

PROPRIETARY AND CONFIDENTIAL
THE INFORMATION CONTAINED IN
THIS DRAWING IS THE SOLE PROPERTY
OF KANG YANG HARDWARE
ENTERPRISE CO. ANY
REPRODUCTION IN PART OR AS A
WHOLE WITHOUT THE WRITTEN
PERMISSION OF
KANG YANG HARDWARE ENTERPRISE
CO. IS PROHIBITED.

DO NOT SCALE DRAWING

DATE
2016.05.20

DRAWN
Y.C.P

CHECKED
林祺翔

APPROVED
Kang

TITLE
HEAT SINK RIVET(BODY)

MATERIAL
SEE ABOVE

COLOR
SEE ABOVE

FINISH
UNLESS OTHERWISE SPECIFIED
TOLERANCE: SEE ABOVE

DWG. NO.

HSR-93A

SIZE
A4

SCALE: 3:1

PART NO.

SEE ABOVE

SPEC. DWG

REV
D

UNIT
mm

SHEET 1 OF 1