


MOUNTING HOLE $\phi 3.2$
THICKNESS 1.6~1.8mm



MOUNTING HOLE $\phi 3.2$
THICKNESS 1.6mm

NOTE: 1. SHRINKING IS NORMAL STATUS.
內縮為正常現象。
2. MADE OF EQUIVALENT MATERIAL.
均可使用同等材質。

K
ISO 9001
ISO 14001
QC 080000
IATF 16949

康揚企業股份有限公司
KANG YANG HARDWARE ENTERPRISE CO., LTD.
康揚塑膠(東莞)有限公司
KANG YANG PLASTIC(DONG GUAN)CO., LTD.
康哲電腦配件(吳江)有限公司
KANG CHE COMPUTER COMPONENTS(WUJIANG)CO., LTD.

| | | | | | | | | |
|---|----------|------------|---|------------------|--------|----------|--------------|----------|
| PROPRIETARY AND CONFIDENTIAL THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF KANG YANG HARDWARE ENTERPRISE CO. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF KANG YANG HARDWARE ENTERPRISE CO. IS PROHIBITED. | DATE | 2007.09.06 | TITLE | SPACER SUPPORT | | DWG. NO. | PART NO. | |
| | DRAWN | BUNNY | MATERIAL | NYLON 66 UL94V-2 | | LMSP-9.5 | | LMSP-9.5 |
| | CHECKED | 李柏青 | COLOR | NATURAL | FINISH | SIZE | SPEC. DWG | REV |
| | APPROVED | Kang | UNLESS OTHERWISE SPECIFIED TOLERANCE: SEE ABOVE | | A4 | A | | |
| DO NOT SCALE DRAWING | | | | SCALE: 3:1 | UNIT | mm | SHEET 1 OF 1 | |