




HOLE IN CHASSIS: $\phi 4.75$ mm^{±0.08}
 CHASSIS THICKNESS: 1.6mm

NOTE: 1. SHRINKING IS NORMAL STATUS.
 內縮為正常現象.
 2. MADE OF EQUIVALENT MATERIAL.
 均可使用同等材質.



康揚企業股份有限公司
 KANG YANG HARDWARE ENTERPRISE CO., LTD.
 康揚塑膠(東莞)有限公司
 KANG YANG PLASTIC(DONG GUAN)CO.,LTD.
 康哲電腦配件(吳江)有限公司
 KANG CHE COMPUTER COMPONENTS(WUJIANG)CO.,LTD.

PROPRIETARY AND CONFIDENTIAL THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF KANG YANG HARDWARE ENTERPRISE CO. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF KANG YANG HARDWARE ENTERPRISE CO. IS PROHIBITED. DO NOT SCALE DRAWING	DATE	2019.05.21	TITLE	WIRE MOUNT	DWG. NO.	PART NO.	
	DRAWN	FORSEN	MATERIAL	NYLON 66 UL94V-2		SLCD-9.5	
	CHECKED	彭永承	COLOR	NATURAL	SIZE	SPEC. DWG.	REV
	APPROVED	Kang	FINISH		A4		A
			UNLESS OTHERWISE SPECIFIED TOLERANCE: SEE ABOVE		SCALE: 2:1	UNIT mm	SHEET 1 OF 1